



LEGEND

- | | | | |
|--------------------------|----------------------------|---------------------|-------------------------|
| Intake Air | Belt Line | Last Open Cross-Cut | Bleeder Measurement Pt. |
| Return Air | Belt Air | Evaluation Point | Bleeder Block |
| Primary Escapeway | Secondary Escapeway | Seal (proposed) | Second Mined |
| Overcast (proposed) | Regulator (proposed) | Major Fault | Minor Fault |
| Stopping (proposed) | Stopping w/Door (proposed) | Roof Fall | Roof Fall (cleaned) |
| Air Lock (proposed) | Curtain (proposed) | Lease Line | Section Line |
| Line Brattice (proposed) | | | |

Second Mining

CERTIFICATION STATEMENT:

I, the undersigned, hereby certify that this map is, to the best of my knowledge and belief, correct, and that it shows the information required by 30 CFR 75.372 and 30 CFR 75.1200.
The map covers the period ending: _____
Signature: _____
Registration Number: _____

The person(s) responsible for the information on this map are:
M. D. Waymott
J. M. Walters

MSHA Mine ID No. 42-02074

Lodestar Energy, Inc.

Mountain Operations, Horizon Mine
HC 35, Box 370 Helper, Utah 84526

Phone: (435) 637-9200 Fax: (435) 448-9456

THIS COAL ISOPACH MAP - A SEAM - UPPER SPLI

Size: Drawn By: DMG No:
D KP

Scale: 1" = 500' Date: October 14, 1999 Sheet: